SHIVAM GAUR &ASSOCIATES

M.C.D. APPROVED STRUCTURAL ENGINEER (SE/0674) 110, F.F. Surana Bhawan, Vikas Marg, Laxmi Nagar, Delhi-92, E mail:- sgaur603@gmail.com

Date :- 24/04/2024

STRUCTURE STABILITY CERTIFICATE

<u>PROPERTY NO</u>- BLOCK 1 (GROUND + 3) & BLOCK 2 (BASEMENT + GROUND + 3) AT BANYAN TREE SCHOOL (A UNIT OF RAM KRISHAN & SONS CHARITABLE TRUST), 3, LODHI INSTITUTIONAL AREA, LODHI ROAD, NEW DELHI - 110003.

This is to certify that the existing structure was personally surveyed by me in presence of **Mr. O. P. Sharma**, **Manager of School**. I found that the brick was of sufficient thickness to bear the loads of roofs, there are no cracks in their as present. I also found that there is no basic causes of failure i.e water logging in the street and in drains or nearby of premises, dampness / leakage in roof etc. Provisions regarding Earthquake resisting building for Zone IV have been taken into consideration for Structural Design as per Indian Standard Code IS: 1893: 2016 (Code for Earthquake Design of Structures)

As such, the existing structure is safe and sound.

Signature of owner

Name in block letters

MCD Regd. Engineer (SE/0674 & E/00726

110, F.F. Surana Bhawan, Vikas Marg, Delhi-110092

Signature of structure engineer

Name in block letters with stamp